



City of Watauga's
Open Records Request
 Month of November, 2014

Case Type	Case Description	Initial Inspection Date	Short Address
Exterior Property	Garage door must be repaired. Any rotted wood must be removed. Peeling paint must be corrected.	11/03/2014	6728 Lyndale
Exterior Property	The home located at 6728 Lyndale Drive has unsightly conditions. The garage door has been damaged for several months. The damage continues to worsen. Junk in the garage is visible and protruding through damaged door. Please make the residents repair the door. Our city is getting junkier by the day. Don't let it happen. Thank you.	11/20/2014	6728 Lyndale
Exterior Property			
Total Cases:		2	
Exterior Structure	Columns on carport must be covered with brick or stone. Carport must also be painted to match trim of home.	11/03/2014	6724 Echo Hill
Exterior Structure	Garage door must be repaired....has rotted wood and broken window.	11/17/2014	6657 Greendale
Exterior Structure			
Total Cases:		2	
TOTALS:	Total Cases:	4	