



City of Watauga's  
**Open Records Request**  
 Month of October, 2014

Case Type	Case Description	Initial Inspection Date	Short Address
Exterior Property	Peeling paint must be corrected. Rotted wood must be removed. Garage door must be weather tight.	10/09/2014	6516 Old Mill
Exterior Property	Roof must be repaired.	10/10/2014	6609 Avalon
Exterior Property	Garage doors must be installed, or a permit must be obtained for a garage conversion.	10/21/2014	6701 Brookdale
Exterior Property	Property must be maintained, fences, accesoorry buildings, and debris littered yards, must be kept in working order	10/29/2014	5865 Haney
Exterior Property	Rotted wood must be removed. Peeling paint must be corrected.	10/30/2014	6404 Old Mill
<b>Exterior Property</b>			
Total Cases:		<b>5</b>	
Exterior Structure	Please repair all peeling paint and rotting wood. You have been sent previous warning on 8/13/14. You have 30 days to complete repairs or a citation will be issued to Maurice Dubois.	10/03/2014	5916 Lalagray
Exterior Structure		10/16/2014	6236 Brookside
Exterior Structure	Please repair all rotting wood and peeling paint	10/14/2014	6004 Barry
Exterior Structure	Peeling paint and rotting wood must be repaired	10/20/2014	6905 Bennington
Exterior Structure	Please replace or remove torn tarp around	10/16/2014	7501 Evergreen

	carport.		
Exterior Structure	Roof must be repaired of all missing, loose or bad shingles.	10/17/2014	8029 Berry Brook
Exterior Structure	Please paint all raw areas	10/29/2014	6420 Kennedy
Exterior Structure	Please paint all peeling or chipping paint	10/29/2014	5912 Emerson
Exterior Structure	Repair rotting or damaged trim, paint all peeling paint	10/29/2014	5865 Haney
<b>Exterior Structure</b>			
Total Cases:		<b>9</b>	
Vacant Property High Weeds	Original case # 14-02082 on file; repeat offense, assigning to contractor.	10/28/2014	6201 North Park
Vacant Property High Weeds		10/30/2014	6300 N Stardust
<b>Vacant Property High Weeds</b>			
Total Cases:		<b>2</b>	
Vacant Property Swimming Pool Maintenance	Pool must be treated and maintained.	10/21/2014	6824 Brookdale
<b>Vacant Property Swimming Pool Maintenance</b>			
Total Cases:		<b>1</b>	
Vacant Property-Condemnation of Property	Location has been declared condemned by the City of Watauga. Next step would be demolition if not brought into compliance.	10/17/2014	5649 Linda
Vacant Property-Condemnation of Property	This property has been condemned by the City of Watauga. The next step is demolition if the property is not brought into compliance.	10/17/2014	6608 Emily
Vacant Property-Condemnation of Property	This property has been condemned by the City of Watauga. The next step is demolition if the home is not brought into compliance.	10/17/2014	6540 Avalon
<b>Vacant Property-Condemnation of Property</b>			

Total Cases:	3
--------------	---

Water Drainage	Gutter must not allow water to stand between homes, please direct water at the bottom of gutter in the direction of the street away from homes.	10/23/2014	7609 Meadowbrook
----------------	-------------------------------------------------------------------------------------------------------------------------------------------------	------------	------------------

**Water Drainage**

Total Cases:	1
--------------	---

<b>TOTALS:</b>	Total Cases:	21
----------------	--------------	----